Description	Cat. No.
1Torch® Consuma	bles /
0-Ring	8-3487
0-Ring	8-3486
Electrode, MaximumLife®	9-8215
Start Cartridge	9-8213
Tip, 40A, Cutting	9-8208
Tip, 50/55A, Cutting	9-8209
Tip, 60A, Cutting	9-8210
Tip, 70A, Cutting	9-8231
Tip, 80A, Cutting	9-8211
Tip, 90/100A, Cutting	9-8212
Tip, A, (40A) Gouging	9-8225
Tip, B, Gouging	9-8226
Tip, C, Gouging	9-8227
Tip, D, Gouging	9-8228
Shield Cup	9-8218
Shield Cup Body, MaximumLife®	9-8237
Shield Cap, Mach, 50-60A	9-8238
Shield Cap, Mach, 70-100A	9-8239
Shield Cap, Deflector	9-8243
Shield Cap, Gouging	9-8241
Ohmic Clip	9-8224
Spare Parts Kit, 40 Amp	5-2551
Spare Parts Kit, 50/55 Amp	5-2552
Spare Parts Kit, 60 Amp	5-2553
Spare Parts Kit, 70 Amp	5-2554

Spare Parts Kit, 80 Amp


Spare Parts Kit, 90/100 Amp

/ Parts

5-2555

5-2556

SL100® 1Torch Mechanized Torch Parts



(Note: All Spare Parts Kits include ten (10) Tips, five (5) Electrodes and one (1) Start Cartridge.)